OUNTRY Dast Germany	
	REPORT
OPIC Briesen Airfield	CAST CAST
	25
VALUATIONPLACE OBTA	
ATE OF CONTENT.	
AYE OBTAINED	4 January 1959 25X
FERENCES	
IGES 1 ENCLOSURES (NO. & TYPE)	Comment of the second
EMARKS	25X
This is UN	NEVALUATED Information
	·
<u> </u>	:2:: L (**
lights were lighted-up on the aircraft airfield. The lights which were fitted turned off when the aircraft touched g	in the vicinity of the engines were
flight control station adiated its li 1400 on 30 November, Il 26s made 14 30 at an altitude of 500 meters and wisib temporarily aloft at the same time. The were not in operation although wisibil of observation, only 23 Il-28s were pa	thed on and a red search ight near the the ght vertically upward. In tween 1000 and the minute flights. There was a 10/10 the sale ility of 1 km. Tour aircraft were a lighting facilities along the runway ity was poor. During the entire period the ranked on the usual dispersal areas along the aft were possibly parked in the southwestern
flight control station adiated its li 1400 on 30 November, Il 28s made 14 30 at an altitude of 500 meters and wisib temporarily aloft at the same time. The were not in operation although visibility of observation, only 23 Il-28s were particle southern taxiway. Additional aircrecorner of the field. 1	thed on and a red search ight near the the ght vertically upward. In tween 1000 and the minute flights. There was a 10/1000 meast ility of 1 km. Tour aircraft were a lighting facilities along the runway ity was poor. During the entire period that were nessibly parked in the southwestern
flight control station addiated its li 1400 on 30 November, Il-28s made 14 30- at an altitude of 500 meters and wisib- temporarily aloft at the same time. The were not in operation although wisibil of observation, only 23 II-28s were par- the southern taxiway. Additional aircra corner of the field. 1	the don and a red sear light near the the ght vertically upward. In tween 1000 and the minute flights. There was a 10/10 the east lility of 1 km. Sour aircraft were a lighting facilities along the runway ity was poor. During the entite period the usual dispersal areas along that were resibly parked in the southwestern aft were resibly parked in the airfield: